

Township of Union School District Ventilation Report 2021-2022

**Based on data from EI Associates
Architects & Engineers**

Key:

Roof Top Ventilation: unit on top of roof that provide heat, air conditioning, and fresh air

Air Handler Ventilation: unit with condenser on roof; air “handler” is in classroom

Univent Ventilation: unit inside classroom that provides heat, air conditioning, and fresh air

Board of Education Township of Union Ventilation Report

School	Room #	Windows	Univents	Roof Tops	Air Handlers	Window A/C
UHS	First Floor					
UHS	A100	X		X		
UHS	A101	X		X		
UHS	A102	X			X	
UHS	A103	X			X	
UHS	Band Room	X			X	
UHS	A105	X			X	
UHS	A106	X	X			
UHS	A107	X	X			
UHS	A108	X	X			
UHS	A109	X	X			
UHS	A110	X	X			
UHS	A111	X	X			
UHS	A112	X	X			
UHS	A113	X	X			
UHS	B100				X	
UHS	B101	X	X			
UHS	B102				X	
UHS	B104				X	
UHS	B105	X	X			
UHS	B106	X	X			
UHS	B107	X	X			
UHS	C101	X	X			
UHS	C102	X	X			
UHS	C103	X			X	
UHS	C104	X			X	
UHS	C105	X	X	X		
UHS	C106			X		
UHS	C107			X		
UHS	C108			X		
UHS	C109	X	X			
UHS	C110	X	X			
UHS	C111	X	X			
UHS	C113	X	X			
UHS	C114	X	X			
UHS	C115	X	X			
UHS	C116	X	X			
UHS	C117	X	X			
UHS	C119	X			X	
UHS	C120	X	X			
UHS	C121	X	X			
UHS	C122	X	X			
UHS	C123	X	X			
UHS	C124	X	X			
UHS	C125	X	X			
UHS	C126	X	X			
UHS	C127	X	X			
UHS	C128	X	X			

Board of Education Township of Union Ventilation Report

School	Room #	Windows	Univents	Roof Tops	Air Handlers	Window A/C
UHS	First Floor					
UHS	C129	X	X			
UHS	G101	X	X			
UHS	G102	X	X			
UHS	G103	X	X			
UHS	G104	X	X		X	
UHS	G105				X	
UHS	G106	X		X		
UHS	G107	X			X	
UHS	G108	X			X	
UHS	G109	X	X			
UHS	G110	X		X		
UHS	G111	X	X			X
UHS	G113	X	X			
UHS	G114	X	X			
UHS	G115	X	X			
UHS	G116	X	X			
UHS	G117	X	X			
UHS	G118	X	X			
UHS	G119	X	X			
UHS	G120	X	X			
UHS	G121	X	X			
UHS	G122	X	X			
UHS	G123	X	X			
UHS	L100D	X	X			
UHS	L101			X		
UHS	L102	X	X			
UHS	L103	X	X			
UHS	L104	X	X			
UHS	L105	X	X			
UHS	L106	X	X			
UHS	L107	X	X			
UHS	L108	X	X			
UHS	L109	X	X			
UHS	L110	X	X			
UHS	CST014				X	
UHS	O11	X			X	
UHS	O12	X				X
UHS	O12A	X				X
UHS	O12B	X				X
UHS	Second Floor					
UHS	D201	X	X			
UHS	D202	X	X			
UHS	D203	X	X			
UHS	D204	X	X			
UHS	D205	X	X			
UHS	D206	X	X			
UHS	D207	X	X			

Board of Education Township of Union Ventilation Report

School	Room #	Windows	Univents	Roof Tops	Air Handlers	Window A/C
UHS	First Floor					
UHS	D208	X	X			
UHS	D209	X	X			
UHS	D210				X	
UHS	D211	X	X			
UHS	D212	X	X			
UHS	D213	X	X			
UHS	D214	X	X			
UHS	D215				X	
UHS	D216	X	X			
UHS	D217	X	X			
UHS	D218	X	X			
UHS	D219	X	X			
UHS	D220	X	X			
UHS	D221	X	X			
UHS	D222	X	X			
UHS	D223	X	X			
UHS	D224	X	X			
UHS	D225	X	X			
UHS	D226	X	X			
UHS	D227	X	X			
UHS	D228	X	X			
UHS	D229	X	X			
UHS	D230	X	X			
UHS	D231	X	X			
UHS	D232	X	X			
UHS	D233			X		
UHS	D234	X	X			
UHS	D237	X	X			
UHS	D238	X	X		X	
UHS	D239	X	X			
UHS	D240	X	X		X	
UHS	D241	X	X			
UHS	D242	X	X			
UHS	D243	X	X			
UHS	D244				X	
UHS	D245	X	X			
School						
BMS	First Floor					
BMS	101	X	X			
BMS	103	X	X			
BMS	105	X	X			
BMS	113	X	X			
BMS	117	X	X			X
BMS	119	X	X			X
BMS	121	X	X			X
BMS	122	X	X			
BMS	123	X	X			X

Board of Education Township of Union Ventilation Report

School	Room #	Windows	Univents	Roof Tops	Air Handlers	Window A/C
UHS	First Floor					
BMS	125	X	X			
BMS	127	X	X			X
BMS	131	X	X			X
BMS	133	X	X			
BMS	135	X	X			
BMS	136	X	X			
BMS	137	X	X			
BMS	139	X	X			X
BMS	141	X	X			
BMS	140	X	X			X
BMS	151	X	X		X	X
BMS	Second Floor					
BMS	201	X	X			
BMS	202	X	X			
BMS	203	X	X			
BMS	205	X	X			X
BMS	207	X	X			
BMS	208	X	X			
BMS	209	X	X			
BMS	210	X	X			
BMS	211	X	X			X
BMS	213	X	X			X
BMS	215	X	X			X
BMS	217	X	X			X
BMS	218	X	X			
BMS	219	X	X			X
BMS	221	X	X			
BMS	223	X	X			X
BMS	224	X	X			
BMS	225	X	X			X
BMS	227	X				X
BMS	229	X	X			X
BMS	231	X	X			
BMS	233	X	X			
BMS	237	X	X			X
BMS	238	X	X			X
BMS	241	X	X			
BMS	245	X	X			X
BMS	247	X	X			
BMS	249	X	X			
BMS	251	X	X			
BMS	255	X	X			
BMS	259	X				
BMS	263	X	X			
BMS	265	X	X			X
BMS	Third Floor					
BMS	301	X	X			X
BMS	302	X	X			X
BMS	303	X	X			X

Board of Education Township of Union Ventilation Report

School	Room #	Windows	Univents	Roof Tops	Air Handlers	Window A/C
UHS	First Floor					
BMS	304	X	X			
BMS	305	X	X			X
BMS	307	X	X			X
BMS	310	X	X			X
BMS	311	X	X			
School						
KMS	Ground Floor					
KMS	1	X	X			
KMS	2	X				X
KMS	3	X	X			X
KMS	5	X	X			X
KMS	13	X	X			X
KMS	15	X	X			
KMS	16	X	X			
KMS	17	X	X			
KMS	19	X	X			
KMS	20	X	X			
KMS	22	X	X			
KMS	23	X	X			X
KMS	24	X			X	X
KMS	25	X			X	
KMS	First Floor					
KMS	101	X	X			
KMS	102	X	X			
KMS	104	X	X			X
KMS	107	X	X			X
KMS	114	X	X			X
KMS	121	X	X			X
KMS	123	X	X			
KMS	125	X	X			X
KMS	126	X	X			
KMS	128	X	X			
KMS	129	X	X			
KMS	130	X			X	
KMS	131	X			X	
KMS	Second Floor					
KMS	201	X	X			
KMS	202	X	X			X
KMS	203	X	X			X
KMS	205	X	X			X
KMS	206	X	X			X
KMS	207	X	X			X
KMS	209	X	X			X
KMS	214	X	X			
KMS	216	X	X			X
KMS	217	X	X			
KMS	218	X	X			
KMS	220	X	X			
KMS	221	X	X			
KMS	222	X	X			
KMS	223	X	X			

Board of Education Township of Union Ventilation Report

School	Room #	Windows	Univents	Roof Tops	Air Handlers	Window A/C
UHS	First Floor					
KMS	224	X			X	
KMS	225	X			X	
JS	First Floor					
JS	102	X		X		
JS	104	X		X		
JS	105	X		X		
JS	106	X		X		
JS	107	X		X		
JS	108	X		X		
JS	109	X		X		
JS	110	X		X		
JS	111	X		X		
JS	Second Floor					
JS	201	X	X			
JS	202	X	X			
JS	203	X	X			
JS	205	X	X			
JS	207	X	X			
JS	209	X		X		
JS	210	X		X		
JS	211	X		X		
JS	212	X		X		
JS	213	X		X		
JS	214	X		X		
JS	215	X		X		
JS	216	X		X		
JS	217	X		X		
JS	218	X		X		
JS	222A	X		X		
JS	Third Floor					
JS	301	X		X		
JS	302	X		X		
JS	303	X		X		
JS	304	X		X		
JS	305	X		X		
JS	306	X		X		
JS	307	X		X		
JS	308	X		X		
School						
BH	First Floor					
BH	1	X	X			X
BH	2	X	X			X
BH	3	X	X			X
BH	4	X	X			X
BH	5	X	X			X
BH	6	X	X			X
BH	7	X	X			X
BH	8	X	X			X
BH	9	X	X			X

Board of Education Township of Union Ventilation Report

School	Room #	Windows	Univents	Roof Tops	Air Handlers	Window A/C
UHS	First Floor					
BH	10	X	X			X
BH	11	X	X			X
BH	12	X	X			X
BH	13	X	X			X
BH	14	X	X			X
BH	15	X	X			X
BH	16	X	X			X
BH	17	X	X			X
BH	18	X	X			X
BH	19	X	X			X
BH	20	X	X			X
BH	21	X	X			X
BH	22	X	X			X
BH	23	X	X			X
BH	24	X	X			X
BH	25	X	X			X
BH	Second Floor					
BH	26	X	X			X
BH	27	X	X			X
BH	28	X	X			X
BH	29	X	X			X
BH	30	X	X			X
BH	31	X	X			X
BH	32	X	X			X
School						
CF	Basement					
CF	1	X				
CF	2	X				
CF	3	X				
CF	4	X				
CF	First Floor					
CF	101	X	X			
CF	102	X	X			
CF	103	X	X			
CF	104	X	X			
CF	105	X	X			
CF	106	X	X			
CF	108	X	X			
CF	111	X	X			
CF	112	X	X			
CF	113	X	X			
CF	115	X	X			
CF	Second Floor					
CF	201	X	X			
CF	202	X	X			
CF	203	X	X			
CF	204	X	X			
CF	205	X	X			
CF	206	X	X			
CF	208	X	X			
CF	211	X	X			

Board of Education Township of Union Ventilation Report

School	Room #	Windows	Univents	Roof Tops	Air Handlers	Window A/C
UHS	First Floor					
CF	212	X	X			
CF	213	X	X			
CF	215	X	X			
School						
FS	First Floor					
FS	1	X	X		X	
FS	2	X	X		X	
FS	3	X	X		X	
FS	4	X	X		X	
FS	5	X	X		X	
FS	6	X	X		X	
FS	7	X	X		X	
FS	8	X	X		X	
FS	9	X	X		X	
FS	10	X	X		X	
FS	11	X	X		X	
FS	12	X	X		X	
FS	Second Floor					
FS	13	X	X		X	
FS	14	X	X		X	
FS	15	X	X		X	
FS	16	X	X		X	
FS	17	X	X		X	
FS	18	X	X		X	
FS	19	X			X	
FS	20	X	X		X	
FS	21	X	X		X	
FS	22	X	X		X	
FS	23	X	X		X	
FS	24	X	X		X	
FS	25	X	X		X	
FS	26	X	X		X	
FS	27	X	X		X	
School						
HC	First Floor					
HC	126	X	X			
HC	127	X	X			
HC	128	X	X			
HC	129	X	X			
HC	130	X	X			
HC	131	X	X			
HC	133	X	X			
HC	134	X	X			
HC	136	X	X			
HC	138	X	X			
HC	139	X	X			
HC	141	X	X			
HC	162	X	X			
HC	166	X	X			
HC	167	X	X			
HC	170	X		X		

Board of Education Township of Union Ventilation Report

School	Room #	Windows	Univents	Roof Tops	Air Handlers	Window A/C
UHS	First Floor					
HC	174	X	X			
HC	175	X	X			
HC	184	X	X			
HC	185	X	X			
HC	186	X	X			
HC	188	X	X			
HC	190	X		X		
HC	192	X		X		
HC	193	X		X		
HC	195	X		X		
HC	196	X		X		
HC	197	X		X		
HC	198	X		X		
HC	Second Floor					
HC	203	X	X			
HC	204	X	X			
HC	206	X	X			
HC	207	X	X			
HC	208	X	X			
HC	209	X	X			
HC	210	X	X			
HC	212	X	X			
School						
LS	First Floor					
LS	101	X	X			X
LS	102	X	X			X
LS	103	X	X			X
LS	104	X				
LS	105	X	X			X
LS	107	X	X			X
LS	109	X	X			X
LS	112	X	X			X
LS	113	X	X			X
LS	114	X	X			X
LS	115	X	X			X
LS	116	X	X			
LS	117	X	X			X
LS	Second Floor					
LS	201	X	X			X
LS	202	X	X			X
LS	203	X	X			X
LS	204	X	X			X
LS	205	X	X			X
LS	206	X	X			X
LS	207	X	X			X
LS	208	X	X			X
LS	209	X				X
LS	210	X	X			X
LS	211	X	X			X
LS	212	X	X			X
LS	213	X	X			X

Board of Education Township of Union Ventilation Report

School	Room #	Windows	Univents	Roof Tops	Air Handlers	Window A/C
UHS	First Floor					
LS	214	X	X			X
LS	215	X	X			X
LS	216	X	X			
School						
WS	Ground Floor					
WS	100A	X	X			X
WS	100B	X	X			X
WS	First Floor					
WS	101	X	X			
WS	102	X	X			
WS	103	X	X			
WS	104	X	X			
WS	105	X	X			X
WS	112	X	X			
WS	114	X	X			
WS	115	X	X			
WS	121	X	X			
WS	122	X	X			
WS	125	X	X			
WS	126	X	X			X
WS	127	X	X			
WS	Second Floor					
WS	201	X	X			
WS	202	X	X			
WS	203	X	X			
WS	204	X	X			
WS	205	X	X			X
WS	209	X	X			
WS	213	X	X		X	
WS	215	X	X			
WS	217	X	X			
WS	218	X	X			
WS	221	X	X			
WS	222	X	X			
WS	225	X	X			
WS	227	X	X			
WS	228	x	x			